


펌프 수리 진행도

모델명 NM 1/AE-60-0.37kw



1. 펌프 모터 분해 작업

수리 전 펌프 전경



1



2



4



3



2. 펌프 모터 OVERHAUL 작업

수리 후 누압 테스트 전경



1



2



4



3

