


펌프 수리 진행도

모델명 NM 32/16B-60/A-1.5kw



2. 펌프 모터 OVERHAUL 작업

수리 후 누압 테스트 전경




1



2



3



6



5



4

